
HOUSE FINISH AREA


BASEMENT: 1,026 SF FIRST FLOOR: 1,140 SF SECOND FLOOR: 962 SF

TOTAL HOUSE AREA: 3,128 SF



m bath

3 second floor scale 1/4" = 1'-0"



FLOOR PLANS

GOULD RD HOUSE

33

33 N Gould Rd Bexley, OH 43209

A1

3 site plan
| SCALE 1/8" = 1'-0"



VIEWS

33 N Gould Rd Bexley, OH 43209

33

33

ELEVATIONS

33 N Gould Rd Bexley, OH 43209

WINDOW SCHEDULE				
Type Mark	Width	Height	Comments	
	3' - 0"	5' - 0"		
	2' - 6"	4' - 0"		
}	3' - 0"	3' - 6"		

3' - 0" 4' - 0"

- ASPHALT SHINGLE ROOFING


SIDING AND TRIM

2ND FLOOR



west elevation


SCALE 1/4" = 1'-0"



east elevation
SCALE 1/4" = 1'-0"

Scale 1/4" = 1'-0"	
	ASPHALT SHINGLE ROOFING
	WINDOW HEAD 0L
	2ND FLOOR
	WINDOW HEAD SIDING AND TRIM
	1ST FLOOR
2 north elevation SCALE 1/4" = 1'-0"	

A-2



GOULD RD HOUSE 33

33 N Gould Rd Bexley, 0H 43209

GARAGE PLANS

The structure located at 33 North Gould Road cannot be determined to be of historical or architecturally significant.

There is nothing architecturally significant to the design or construction to the dwelling. Structure is based on a four foot, block, crawl space foundation. Dimensions for the general construction follow standard size lumber. The rear of the house, 25′ 6″ wide, is constructed with 12′ and 14′ lumber for the floor and roof, allowing enough material to rest on the load bearing members without cutting. The floor for the front of the dwelling is based on 16′ lumber, the roof timbers are 18 feet. With a flat roof (actual slope is 23/64″ over 12″), the concept is based on the minimalist construction material and waste. There was only one wooden door installed on the bathroom, the bedroom and hall closets had no doors only curtains covering the openings, and the bedrooms had vinyl accordion doors.

The architect and builder are not known, if an architect was used. The dwelling was constructed for restaurateurs Joseph and Bernice Alexander. It is presumed they had the house built 1951 for them to be close by to oversee the construction of their future restaurant and supper club The Desert Inn, located at approximately 3550 East Broad Street. The Desert Inn opened for business in 1953. The two of them operated the business until 1983 when it was sold. Joseph passed 1985, and Bernice passed in January 2003. The current owner purchased the property 33 North Gould Road from the estate in February 2003.

Factors determining renovation vs. new construction. These are factors considered over 20 years of ownership:

- Flat roof; Current roof has four layers of rolled asphalt roofing material, at a
 considerable weight. Over 1,300 Sq/ft of roof slopes to the North/East corner of
 dwelling with one down spout. There is a history of constant water migrating
 between the stone and stucco front walls of the house. The sill plate below this
 area was replaced in 2004. Even surrounding ranch dwellings of similar
 construction have gabled roofs.
- No garage; no secure storage of vehicle or yard equipment. Current site plan only avails a garage to be located on the front of the dwelling. In a smaller footprint then the current carport. Or, a single car garage on the Southwest corner of the lot.
- The current carport is approx. 19' X 20', with no inner supports. Assuming the current carport has the same four layers of asphalt roofing as the main dwelling, and an approximate 3/4" to one inch of stucco on the underside, totals an immense dead load. The carport is only anchored to the roofline of the main dwelling and supports on the southern edge, I feel, makes this a structural

hazard. The weight of the carport roof is pulling down the roof of the main dwelling.

- Unknown when purchased, the crawlspace had a significant flooding issue. This
 was not discovered until the beginning of 2004. In times of a moderate rain,
 would increase the water table, flooding the complete crawlspace approx. 12
 inches. Installation of a sump pit and French drain remediated most of this
 problem. Though never tested, the underside of the flooring may pose a mold
 issue.
- The idea of expansion upward has been looked into for creation of more living space. Even if the existing foundation could support the addition of the weight of the upper floor, the almost bigger issue is dealing with the slight slope of the roofline. The slope is mimicked in the ceiling in the living space, to level this surface would require the removal of the entire roof and ceiling. And then, build up all existing walls to match the tallest wall on the South side, this would require the an addition of approx. 8 inches to the North wall, and varying amounts to all intermediate, and end walls.

To summarize the issues as we see them:


No secure storage outside the house, for vehicles, lawn equipment, and other necessities. Removal of existing carport is required.

Existing roof condition has to be dealt with.

No interior storage, few closets (a total of five) and are typical of the time of construction 3-4 feet wide by 2 feet deep.


Only two bedrooms, both of modest size compared to today's standard, are 12×13 feet, the second is 9×12 feet.

TOTAL HOUSE AREA: 3,128 SF



m bath

3 second floor scale 1/4" = 1'-0"





33 N Gould Rd Bexley, 0H 43209

FLOOR PLANS

3 site plan SCALE 1/8" = 1'-0"



33

33 N Gould Rd Bexley, OH 43209

VIEWS

A2



- RIDGE VENT

Metal roofing Standing seam


WINDOW HEAD

2ND FLOOR

WINDOW HEAD

- SIDING AND TRIM

1ST FLOOR





ELEVATIONS

A-2

RIDGE VENT ROOFING Metal Roofing Standing seam WINDOW HEAD 2ND FLOOR SIDING AND TRIM WINDOW HEAD 1ST FLOOR

4 south elevation SCALE 1/4" = 1'-0"




2 north elevation SCALE 1/4" = 1'-0"

XASPINIXIXSKINIXIX ROOFING Metal roofing Standing seam WINDOW HEAD 2ND FLOOR , WINDOW HEAD _____ METAL GUTTER AND SIDING AND TRIM __1ST FLOOR ____

west elevation

SCALE 1/4" = 1'-0"

east elevation
SCALE 1/4" = 1'-0"



GOULD RD HOUSE Z 33

33 N Gould Rd Bexley, 0H 43209

GARAGE PLANS

A-5


A Boundary Survey prepared for and certified to:


Paul Kaltenecker

Legal Description: Situated in The State of Ohio, County of Franklin, City of Bexley Being Lot 10 J.L. Davis' 1st Addition, Plat Book

17 Page 254

Posted Address: 33 N. Gould Road, Bexley, Ohio







2740 East Main Street Bexley, Ohio 43209-2577 (614) 235-8677

Telefax 235-4559

Email: info@myerssurveying.com

July 30, 2024

Mr. Paul Kaltenecker

Re: Average Set back distances from #25, 33, 39, 45 & 51 N. Gould Rd. Bexley, OH

Dear Paul,

I measured the setback distance to each of the captioned addresses.

The average setback distance of the five (5) buildings is 45.6 feet.

The setbacks of the individual buildings is:

House No. 25......48.3

House No. 33......45.9

House No. 39......44.5

House No. 45......44.4


House No. 51......44.9

Average of the five houses is 45.6. The most restrictive House No. 25 is 48.3.


Should you have any questions please give me a call.

Sincerely,

Albert J. Myers P.S.









A Boundary Survey prepared for and certified to:

Paul Kaltenecker

Legal Description: Situated in The State of Ohio, County of Franklin, City of Bexley Being Lot 10 J.L. Davis' 1st Addition, Plat Book

17 Page 254

Posted Address: 33 N. Gould Road, Bexley, Ohio

