

236 North Columbia Avenue

PLANT SURVEY *		
A LIQUIDAMBAR styraciflua	Sweetgum	Existing Street Tree- protected
B ACER saccharum	Sugar Maple	Existing Street Tree- protected
C ACER saccharum	Sugar Maple	Existing Street Tree- protected
D TSUGA canadensis	Canadian Hemlock	11" average caliper 16 trees to be removed
E TSUGA canadensis	Canadian Hemlock	12.5" caliper Remove
F ACER saccharum	Sugar Maple	30" caliper Keep and protect
G Mixed understory and volunteers	TAXUS media	5' shrubs To Remove
	White Ash	Under 6" caliper To Remove
	Canadian Hemlock	Average 10" caliper 25 trees to be removed
H TSUGA canadensis	Canadian Hemlock	11.5" caliper Keep and protect
I CORNUS Mas	Cornelian Cherry	10' shrubs Remove
J AMUR Lonicera maackii	Amur Honeysuckle	12' tall Invasive- remove
K PINUS resinosa	Red Pine	21.5" caliper Covered in Wisteria- remove
L AMUR Lonicera maackii	Amur Honeysuckle	12' tall Invasive- remove
M QUERCUS rubra	Northern Red Oak	43" caliper To Remove
N QUERCUS rubra	Northern Red Oak	32.5" caliper To Remove
O QUERCUS rubra	Northern Red Oak	34" caliper To Remove
P ACER palmatum	Japanese Maple	5.5" caliper To Remove
Q ACER griseum	Paperbark Maple	13.5" caliper To Remove
R ACER rubrum	Red Maple	40" caliper Remove
S THUJA occidentalis	American Arborvitae	12' tall shrubs Remove
T LIGUSTRUM vulgare	Common Privet	4' tall hedge To Remove
U Volunteer trees	Celtis occidentalis- Hackberry	9" caliper Volunteer- in fence- remove
	ACER negundo- Boxelder	11" caliper Volunteer- in fence- remove
	PRUNUS serotina- Black Cherry	8" caliper Volunteer- in fence- remove
	KOELREUTERIA paniculata-GoldenRain Tree	12" Volunteer- in fence- remove
V GLEDITSIA triacanthos	Honey Locust	34.5" caliper Keep and protect
W PRUNUS calleryana	Bradford Pear	Average 27" caliper Remove 10 trees
X GINKGO biloba	Maidenhair	30" caliper Keep and protect
Y MALUS x scheideckeri	Flowering Crabapple	8.5" caliper 2 trees - remove
Z TSUGA canadensis	Canadian Hemlock	12" caliper 4 trees - remove

Total Caliper of Trees 1065 inches
 Total Caliper Removals 959 inches


* Details on the condition of the existing trees can be found in the included report from the Master Arborist.

Summary of Tree Removal and Plantings

- Removals**
- 3 Red Oak
 - 10 Bradford Pear
 - 1 Red Pine
 - 46 Canadian Hemlock
 - 4 Ornamental Trees
 - Miscellaneous Volunteer trees, old and invasive shrubs
- Main Tree Removals**

- New Trees**
- 11 Hornbeam
 - 9 Oaks
 - 4 Birch
 - 23 Evergreens
 - 24 Ornamental
 - Mix of Evergreen and blooming shrubs, perennials
- Proposed Tree Plantings**

ROW
0' 10' 20'
1 = 20'-0"



Oakland Design Associates



DRAWN	10/2/24
CHECKED	1" = 20'-0"
DATE	JOB NO.
SCALE	
SHEET	

REVISIONS	BY
10/18/24	HB
10/31/24	HB

Landscaping architecture
Site planning
Construction management
1160 Olde Oakland Park Avenue
Columbus, Ohio 43224
(614) 265-5354

236 North Columbia Ave.
EXLEY, OH
SITE PLAN