

## CODED NOTES 🔾

- 1. EXISTING SHOWER AND CONTROLS TO BE REMOVED. THIS CONTRACTOR TO REMOVE ALL ASSOCIATED SANITARY AND VENT PIPING BACK TO WITHIN 2 L.F. OF NEAREST ACTIVE LATERAL BELOW SLAB/AB. CLG., CAP, AND ABANDON IN PLACE. REMOVE ALL ASSOCIATED COLD AND HOT WATER BACK TO ABOVE CLG., TO WITHIN 2 L.F. OF NEAREST ACTIVE SUPPLY MAINS, CAP, INSULATE AND ABANDON IN PLACE.
- 2. EXISTING AIR DEVICE TO REMAIN.
- 3. EXISTING AIR DEVICE TO BE RELOCATED IN NEW CLG. GRID.
- 4. REMOVE EXISTING AIR DEVICE. CAP DUCT AT MAIN.
- 5. EXISTING DUCTWORK TO REMAIN.
- 6. EXISTING CABINET UNIT HEATER TO REMAIN.
- 7. REMOVE EXISTING CABINET UNIT HEATER.
- 8. EXISTING THERMOSTAT TO BE RELOCATED. SEE SHEET HO1 FOR NEW LOCATION.



A D

architects

221 North 4th St Columbus, Ohio 43215 614-228-2122


2633 Erie Ave, Suite 12 Cincinnati, Ohio 45208 513-321-0444

CONSULTANTS

614-766-4896

KOOI STRUCTURAL ENG.
Sunbury, Ohio 433074
614-218-1607

PRATER ENGINEERING
6130 Wilcox Rd
Dublin, Ohio 43016



## BEXLEY CITY HALL RENOVATIONS

2242 E Main St Bexley, OH 43209

12.06.2024 DRAWING PRINT DATE		
MARK	DATE	DESCRIPTION
	12.06.2024	PERMIT SET

FILE INFO

CAD FILE:

COPYRIGHT: GRA+D ARCHITECTS, 2024

SHEET SIZE: 24" x 36"

DEMOLITION HVAC PLAN

H00-24339.DWG

## PRATER Engineering Associates, Inc.

DRAWN BY N. GHOZAT

Engineering Associates, Inc.

6130 Wilcox Road (614)
Dublin, Ohio 43016 praterenging

(614) 766 4896
praterengineering.com

CHECKED BY
J. LOCKARD P.E. 24339

H00