



CITY OF BEXLEY TREE & PUBLIC GARDENS COMMISSION APPLICATION STAFF REVIEW

Project Name: COGO Clifton Station
 Project Address: Clifton Ave
 Reviewed by: Elena Andrews
elena@designspruce.com
 626-676-3330
 Date: 5-6-19

	Project Description	Completed	Incomplete	Missing	N/A
1a	Application	X			
1b	Project Description	X			
	Research				
2a	Significant examples				X
	Design Documentation Drawings				
3a	Existing conditions photographs	X			
3b	Site plan or location plan	X			
3c	Schematic plan with north arrow and bar scale	X			
3d	Elevations, perspectives, isometrics, axonometrics or detailed model	X			
3e	Existing City trees indicated on plan				X
3f	Proposed vegetation	X			
	Recommended information				
4a	Irrigation and maintenance plans				X
4b	Hardscape layout and materials				X
4c	Lighting locations and specifications				X
4d	Fixtures, furniture and equipment				X
4e	Accessories				X
4f	Buildings				X
4g	Other				

Comments <i>(Italicized comments are from previous review)</i>	
4a	Area will not be irrigated but will be maintained by the City of Bexley.
4g	Plant selection is based on hardy low maintenance plants that will provide a variety of color and texture. Plan has been reviewed and approved by Bill Dorman and Grant Archer.